⁴ / ₄ 3) S	anitiz	ed Co	py Approved f	or Release 20	009/10/29	: CIA	-RDP89B	300569R00	008000900	31-4 (\$\frac{1}{2}\tau_1\tau_2\tau_2\tau_3
444	216	 35Z 1	4 DEC 63		SE	CR	E T	53	ent las principales de proportion e para la companie de la compani	34 m
				it someth	***	A 1 1 1	to the second	3	edgesteren i sageria en sicilière i sono	iz!
10° a 10° g a o ° a g a delega	its at Long side on Pages, and Thomas Report Pages, at	Magazarat i and angle Magazarat na magazarat na magazar	The state of the s			÷	Compression of the compression o		and some special section in the section of the section in the sect	
V.	DI	RECT	OR			•	4		the contract of the second sequences of the second sequences of the second sequences of the	
FROM	14		25X1			• . • •			n i digili masaya karanga masaya karanga karanga karanga karanga masaya. Masaya i masaya masaya masaya karanga sa i galanga karanga karanga karanga karanga karanga karanga karanga kara	original designation of the second of the se
	itte OP	S I-	12				· ::	e ca Market de la care	ROUTIA	
HATO	4							2 1 ((2.6 - 1)	e ver generalis i kapatiti i stepe	A STATE OF THE PROPERTY OF THE
					,	T.		* *		IN 54563
	ΤΛ	Da (00217 14 B	PO 67			•	mag 4/6		1 1 1 1 4 2 0 0
er wastering i ve Bu Linis feet invessely	TO		2201Z 14 D	0.577.5.75 . 4.477 . 4. 20 .	X1====.	i. gr.	- 1222112	tore of the term of the training of the con-	united section 25 of 15 to 15	all delicities in the periodical to
ro			25X1	\$ 1 70					C. Y.	Ø136
	35 LOGS									
	A. 3254									
	8.	342								
	C. 14 DEC 63 FOR 7 PLUS 50									
	D.	HQS	DIR WITH					BIRDW	ATCHER	
	E. HYDRAULIC FLUID FILM ON DRIFT SIGHT GLOBE-REPAIRED SMALL									
	BRAKE LINE LEAK IN NOSE SEC. WASHED EXCESS OIL OUT WITH									
	ALCOHOL. ATTITUDE GYRO OFF FLAG OUT INTERMITTENTLY- REPLACED									
	ATT	TUDE	GYRO.		ſ			<u> </u>		
		NONE						z.		
	F.	14 7 8 2 70					•			
	F.	NONE								

GROUP 1 Eachided from covering Corresponding could declarationals